


Fig. 1A



Start of etch





Fig. 1B



CrOx has been removed





Fig. 2B



Cr has been removed




Fig. 3B

Fig. 3A

Fig. 4A




Fig. 5A




Fig. 6A







Fig. 4B

Fig. 5B

Fig. 6B

Fig. 7





Fig. 8